




Standing in front of river crossing pole on the Alatna side looking at the crossing location



The cable was pulled about one-half mile up the hill to Alatna and readied for pulling under the river. The sheave temporarily mounted to the river crossing pole is visible.



The conduit was pressed with swivels and is being readied for the pull. Somewhere in this pressed area that the cable broke during the pull.




Mark Haas, of Alaska Road Boring, check the depth of the Koyukuk River.




The back side of the drill was tented off with heaters to keep the mud from freezing.



Mark Haas commences drilling.



Mark Haas, Alaska Road Boring, and Dave Callos, of AP&T, test improvised cable reel.



Mark Haas examines damaged conduit before it is spliced.